



Sublimation

Sublimation Temperatures & Press Times

ColorLine Products:

Temperature:	Preheat press to 400°F/204°C.
Recommended Press Time:	60 seconds - unless otherwise noted.
Pressure:	Medium to heavy.
Note:	When pressing large plaques or when pressing a large area of a solid dark color-press, times may need to be increased.

magMATES (Br. Silver, Br. Gold, Brite Gold, Chrome):

Temperature:	Preheat press to 400°F/204°C.
Recommended Press Time:	Press for 10-20 seconds, adjust time as necessary.
Pressure:	Light.
Note:	magMATES may be pressed with the backing down between 2 sheets of Teflon or between 2 pieces of sacrificial paper.

MATES (White):

Temperature:	Preheat press to 400°F/204°C.
Recommended Press Time:	60 - 70 seconds.
Pressure:	Medium to Heavy Pressure.
Note:	White MATES may be pressed with the backing down between 2 pieces of sacrificial paper.



Sublimation

Sublimation Temperatures & Press Times

MATES:

Temperature:	Preheat press to 400 °F/204 °C.
Recommended Press Time:	20-40 seconds.
Pressure:	Light Pressure.
Note:	MATES may be pressed with the backing down between 2 pieces of sacrificial paper

placeMATES:

Temperature:	Preheat press to 400 °F/204 °C.
Recommended Press Time:	60-75 seconds
Pressure:	Light to Medium Pressure.
Note:	If creases appear in the placeMATE - the pressure is too heavy.

mouseMATES:

Temperature:	Preheat press to 400 °F/204 °C.
Recommended Press Time:	60-75 seconds
Pressure:	Light to Medium Pressure.
Note:	If creases appear in the mouseMATE - the pressure is too heavy.

Sublimation

Sublimation Temperatures & Press Times

mugMATES:

Temperature:	Preheat press to 400 °F/204 °C.
Recommended Press Time:	60-75 seconds
Pressure:	Light to Medium Pressure.
Note:	If creases appear in the mugMATE - the pressure is too heavy.